


03630.000187



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
TIMOTHY L. KOHLER, et al.)
Application No.: 09/241,853)
Filed: February 2, 1999)
For: APPLICATION PROGRAMMING)
INTERFACE FOR MEASURING)
DEVICES)
U.S. Patent No.: 6,873,431 B1)
Issued: March 29, 2005)

Examiner: J. Pokrzywa

Group Art Unit: 2622

Certificate
AUG 17 2005
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

08/15/2005 JBALINAN 00000069 6873431

01 FC:1811

100.00 0P

AUG 18 2005

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Attorney for Patentees
Michael K. O'Neill
Registration No.: 32,622

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 99792v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,873,431 *81*

DATED : March 29, 2005

INVENTOR(S) : Timothy L. Kohler, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6

Line 7, "as well" should read --as well as--; and

Line 47, "S." should read --5--.

COLUMN 7

Line 4, "device," should read --devices,--.

COLUMN 8

Line 2, "call," should read --calls,--.

COLUMN 12

Line 12, "program 4B." should read --program 48--.

COLUMN 13

Line 19, "time" should read --times--.

COLUMN 15

Line 19, "functions" should read --functions--; and

Line 20, "of" should read --Of--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,873,431

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)

CA_MAIN 99794 v1

→

AUG 18 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTERS TRIM LINE

PATENT NO. : 6,873,431 B1

DATED : March 29, 2005

INVENTOR(S) : Timothy L. Kohler, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16

Line 17, "is" should read --are--.

COLUMN 20

Line 19, "is: should read --are--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,873,431

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,873,431 B1

DATED : March 29, 2005

INVENTOR(S) : Timothy L. Kohler, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6

Line 7, "as well" should read --as well as--; and

Line 47, "S." should read --5--.

COLUMN 7

Line 4, "device," should read --devices,--.

COLUMN 8

Line 2, "call," should read --calls,--.

COLUMN 12

Line 12, "program 4B." should read --program 48--.

COLUMN 13

Line 19, "time" should read --times--.

COLUMN 15

Line 19, "functions" should read --functions--; and

Line 20, "of" should read --Of--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,873,431

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)

CA_MAIN 99794 v1

→ _____

AUG 18 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,873,431 *B1*

DATED : March 29, 2005

INVENTOR(S) : Timothy L. Kohler, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16

Line 17, "is" should read --are--.

COLUMN 20

Line 19, "is: should read --are--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,873,431

No. of add'l. copies
@ 30¢ per page